

Extraction Oil & Gas, LLC 370 17<sup>th</sup> Street, Suite 5300 Denver, CO 80202

November 19<sup>th</sup>, 2015

Town of Erie 645 Holbrook St. P.O. Box 750 Erie, CO 80516

Re: Notice of Intent to Plug and Abandon Existing Oil & Gas Well

This is a courtesy notice to make the Town of Erie aware of our intent to plug and abandon an oil and gas well located within Erie's municipal boundary. We feel it is important to provide such notice of our proposed activities should any questions arise. Extraction Oil & Gas plans to perform the proposed operation on the following well:

Hippen 1-32 05-123-11395 NWNW-Sec 32-1N-68W

This P&A proposal, approved by the COGCC on November 3<sup>rd</sup>, 2015, will require the use of a small service rig. All access to this location is limited to the access road and all work will be done during daylight hours. We anticipate this activity taking approximately one week to complete.

If you have questions, please contact Extraction Oil & Gas at 720-557-8300.

Thank You,

**Extraction Oil & Gas, LLC** 

FORM 6

Rev 12/05

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894 -2109



DE	ET	OE	ES

## **WELL ABANDONMENT REPORT**

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

Document Number:						
400919008						
Date Received:						

OGCC Operator Number: 10459			Con	tact Name:	Taylor Heffner			
Name of Operator: EXTRACTION OIL & GAS LLC Phone: (720) 9742019								
Address: 370 17TH STREET SUITE 5300 Fax:								
City: DENVER State:	CO Zip	e: <u>8020</u> 2	2Er	mail: theffne	r@extractionog.co	m		
For "Intent" 24 hour notice required, Name: Peterson, Tom Tel: (303) 815-9641								
COGCC contact: tom.peterson@state.co.us								
API Number 05-123-11395-00								
Well Name: HIPPEN			V	Vell Number:	1-32			
Location: QtrQtr: NWNW Se	ection: 32	Tov	vnship: 1N	Range: 68	W Meridi	an: 6		
County: WELD	_	Federal	, Indian or State Leas	e Number:		_		
Field Name: WATTENBERG		Field	Number: 907	750				
Notice of Intent to	Abandon		Subsequen	t Report o	of Abandonm	ent		
Only Complete the Following Background Information for Intent to Abandon  Latitude: 40.012070								
Current and Previously Abandoned Zones								
Formation		erf. Btm	Abandoned Date		l of Isolation	Plug Depth		
CODELL	8034	8042						
J SAND	8468	8478						
NIOBRARA	7599	7917						
Total: 3 zone(s)								
		Casing	<u>History</u>					
Casing Type Size of Hole Size of Casin				ement Cem	ent Bot   Cement	Top Status		

958

8,650

700

295

8+5/8

5+1/2

24

15.5

12+1/4

7+7/8

SURF

1ST

VISU

0

6,310

958

8,650

CIBP #5: Depth with sacks cmt on top.  Set 104 sks cmt from 1150 ft. to 808 ft. Plug Type: STUB PLUG Plug Tagged:  Set sks cmt from ft. to ft. Plug Type: Plug Tagged:  Set sks cmt from ft. to ft. Plug Type: Plug Tagged:  Set sks cmt from ft. to ft. Plug Type: Plug Tagged:  Set sks cmt from ft. to ft. Plug Type: Plug Tagged:  Set sks cmt from ft. to ft. Plug Type: Plug Tagged:  Set sks cmt from ft. to ft. Plug Type: Plug Tagged:  Set sks cmt from ft. to ft. Plug Type: Plug Tagged:  Set sks cmt from ft. to sacks. Leave at least 100 ft. in casing CICR Depth Perforate and squeeze at ft. with sacks. Leave at least 100 ft. in casing CICR Depth Perforate and squeeze at ft. with sacks. Leave at least 100 ft. in casing CICR Depth		#1: Depth	7500 v	with _	58	sacl	ks cmt o	n top. CIPE	3 #2: Depth	with	sacks cmt on top
Set 104 sks cmt from 1150 ft. to 808 ft. Plug Type: STUB PLUG Plug Tagged: X Set sks cmt from ft. to ft. Plug Type: Plug Tagged: Plug Tagged: Set sks cmt from ft. to ft. Plug Type: Plug Tagged: Plug Tagged: Set sks cmt from ft. to ft. Plug Type: Plug Tagged: Plug Tagged: Set sks cmt from ft. to ft. Plug Type: Plug Tagged: Plug Tagged: Set sks cmt from ft. to ft. Plug Type: Plug Tagged: Plug Tagged: Set sks cmt from ft. to ft. Plug Type: Plug Tagged: Set sks cmt from ft. to ft. Plug Type: Plug Tagged: Set sks cmt from ft. to ft. Plug Type: Plug Tagged: Set sks cmt from ft. to ft. Plug Type: Plug Tagged: Set sks cmt from ft. to ft. Plug Type: Plug Tagged: Set sks cmt from ft. to ft. Plug Type: Plug Tagged: Set sks cmt from ft. to ft. With sacks. Leave at least 100 ft. in casing CICR Depth Perforate and squeeze at ft. with sacks. Leave at least 100 ft. in casing CICR Depth (Cast tom Cemert Retainer Depth)  Set 104 sacks half in. half out surface casing from 1150 ft. to 808 ft. Plug Tagged: CicR Depth Set 10 sacks at surface  Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No Set sacks in rat hole Set sacks in mouse hole   Additional Plugging Information for Subsequent Report Only:  Casing Recovered: ft. of inch casing Plugging Date: Set Sacks in mouse hole  Additional Plugging Information for Subsequent Report Only:  Casing Recovered: ft. of inch casing Plugging Date: Set Sacks in mouse hole  Print Name: Taylor Heffner  Trifle: Production Engineer Date: Email: theffner@extractioneg.com  Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.  COGCC Approved: Date: Expiration Date:  CONDITIONS OF APPROVAL, IF ANY: Expiration Date:	CIBP :	#3: Depth	Depth with sacks cmt on top. CIPB #4: Depth				3 #4: Depth	with	sacks cmt on top		
Set sks cmt from ft. to ft. Plug Type: Plug Tagged: Set sks cmt from ft. to ft. Plug Type: Plug Tagged: Set sks cmt from ft. to ft. Plug Type: Plug Tagged: Set sks cmt from ft. to ft. Plug Type: Plug Tagged: Set sks cmt from ft. to ft. Plug Type: Plug Tagged: Set sks cmt from ft. to ft. Plug Type: Plug Tagged: Set sks cmt from ft. to ft. Plug Type: Plug Tagged: Set sks cmt from ft. to ft. Plug Type: Plug Tagged: Set sks cmt from ft. to ft. Plug Type: Plug Tagged: Set sks cmt from ft. to ft. to ft. Plug Type: Plug Tagged: Set sks cmt from ft. with sacks. Leave at least 100 ft. in casing CICR Depth Perforate and squeeze at ft. with sacks. Leave at least 100 ft. in casing CICR Depth (Cast Iron Cement Retainer Depth)  Set 104 sacks half in. half out surface casing from 1150 ft. to 808 ft. Plug Tagged: Set 10 sacks at surface  Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No Set sacks in rat hole Set sacks in mouse hole  Additional Plugging Information for Subsequent Report Only.  Seasing Recovered: ft. of inch casing Plugging Date: Seasong Reco	CIBP	#5: Depth	v	with _		sacl	ks cmt o	n top.			NOTE: Two(2) sacks cemen required on all CIBPs.
Set	Set _	104	sks cmt from	1	150	ft. to	808	ft.	Plug Type:	STUB PLUG	Plug Tagged: 👿
Set sks cmt from ft. to ft. Plug Type: Plug Tagged: Set sks cmt from ft. to ft. Plug Type: Plug Tagged: Set sks cmt from ft. to ft. Plug Type: Plug Tagged: Set sks cmt from ft. to ft. Plug Type: Plug Tagged: Set sks cmt from ft. to ft. to ft. Plug Type: Plug Tagged: Plug Tagged: Set sks cmt from ft. to ft. to ft. Plug Type: Plug Tagged: Set sks cmt from ft. to ft.	Set _		sks cmt from			ft. to		ft.	Plug Type:		Plug Tagged:
Set sks cmt from ft. to ft. Plug Type: Plug Tagged: Perforate and squeeze at ft. with sacks. Leave at least 100 ft. in casing CICR Depth Perforate and squeeze at ft. with sacks. Leave at least 100 ft. in casing CICR Depth Perforate and squeeze at ft. with sacks. Leave at least 100 ft. in casing CICR Depth Core perforate and squeeze at ft. with sacks. Leave at least 100 ft. in casing CICR Depth (Cast Iron Cement Retainer Depth)  Set 104 sacks half in. half out surface casing from 1150 ft. to 808 ft. Plug Tagged: Set 10 sacks at surface  Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No Set sacks in rat hole Set sacks in mouse hole  Additional Plugging Information for Subsequent Report Only  Additional Plugging Information for Subsequent Repor	Set _		sks cmt from			ft. to		ft.	Plug Type:		Plug Tagged:
Perforate and squeeze at ft. with sacks. Leave at least 100 ft. in casing CICR Depth Perforate and squeeze at ft. with sacks. Leave at least 100 ft. in casing CICR Depth Perforate and squeeze at ft. with sacks. Leave at least 100 ft. in casing CICR Depth Cast Iron Coment Retainer Depth)  Set 104 sacks half in. half out surface casing from 1150 ft. to 808 ft. Plug Tagged: Set 10 sacks at surface Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No Set sacks in rat hole Set sacks in rat hole Set sacks in mouse hole  Additional Plugging Information for Subsequent Report Only  Additional Plugging Information for Subsequent Report Only  Wireline Contractor: 'Cementing Contractor: 'Vementing Contract	Set _		sks cmt from			ft. to		ft.	Plug Type:		Plug Tagged:
Perforate and squeeze at ft. with sacks. Leave at least 100 ft. in casing CICR Depth Perforate and squeeze at ft. with sacks. Leave at least 100 ft. in casing CICR Depth CICR Depth (Cast Iron Cement Retainer Depth)  Set 104 sacks half in. half out surface casing from 1150 ft. to 808 ft. Plug Tagged:  Set 10 sacks at surface  Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No Set sacks in rat hole Set sacks in mouse hole  Additional Plugging Information for Subsequent Report Only  Casing Recovered: ft. of inch casing Plugging Date:  Wireline Contractor: Cement and Additives Used:  Covered as a been abandoned per Rule 1103 Yes No ATTACH JOB SUMMARY  Cechnical Detail/Comments:  No ATTACH JOB SUMMARY  Cechnical Detail/Comments: Email: theffner@extractionog.com  Sased on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.  COGCC Approved: Date:  CONDITIONS OF APPROVAL, IF ANY: Expiration Date:  Attachment Check List  Attachment Check List	Set _		sks cmt from			ft. to		ft.	Plug Type:		Plug Tagged:
Perforate and squeeze at ft. with sacks. Leave at least 100 ft. in casing CICR Depth (Cast Iron Cement Retainer Depth)  Set 104 sacks half in. half out surface casing from 1150 ft. to 808 ft. Plug Tagged:  Set 10 sacks at surface  Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No Set sacks in rat hole Set sacks in mouse hole  Additional Plugging Information for Subsequent Report Only  asing Recovered: ft. of inch casing Plugging Date:  Wireline Contractor: 'Cementing Contractor:  ype of Cement and Additives Used:  Iowline/Pipeline has been abandoned per Rule 1103 Yes No ATTACH JOB SUMMARY echnical Detail/Comments:  hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.  Signed: Print Name: Taylor Heffner  Title: Production Engineer Date: Email: theffner@extractionog.com  Sased on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.  COGCC Approved: Date:  Attachment Check List  Attachment Check List	Perfor	ate and so	ueeze at		ft. wit	th		sacks. Lea	ave at least 100	ft. in casing	CICR Depth
Cast tron Cement Retainer Depth	Perfor	ate and so	ueeze at		ft. wit	th		sacks. Lea	ave at least 100	ft. in casing	CICR Depth
Set 10 sacks at surface Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No Set sacks in rat hole Set sacks in mouse hole  Additional Plugging Information for Subsequent Report Only asing Recovered: ft. of inch casing Plugging Date: Wireline Contractor: *Cementing Contractor: type of Cement and Additives Used: lowline/Pipeline has been abandoned per Rule 1103 Yes No *ATTACH JOB SUMMARY echnical Detail/Comments:  Signed: Print Name: Taylor Heffner Title: Production Engineer Date: Email: theffner@extractionog.com  Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.  COGCC Approved: Date:  CONDITIONS OF APPROVAL, IF ANY: Expiration Date:  Attachment Check List  Market Doc Num Name	Perfor	ate and so	ueeze at		ft. wii	th		sacks. Lea	ave at least 100	ft. in casing	CICR Depth (Cast Iron Cement Retainer Depth)
Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No  Set sacks in rat hole Set sacks in mouse hole  Additional Plugging Information for Subsequent Report Only.  Fasing Recovered: ft. of inch casing Plugging Date:  Wireline Contractor: "Cementing Contractor:  Type of Cement and Additives Used:  Towline/Pipeline has been abandoned per Rule 1103 Yes No *ATTACH JOB SUMMARY  Fechnical Detail/Comments:  Signed: Print Name: Taylor Heffner  Title: Production Engineer Date: Email: theffner@extractionog.com  Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.  COGCC Approved: Date:  Attachment Check List  Attachment Check List	_				ut surfac	ce casii	ng from	1150	ft. to 808	_ ft. Plug	Tagged:
Additional Plugging Information for Subsequent Report Only  Casing Recovered:	_				d on nla	ıte	Ahove	Ground D	rv-Hole Marker	■ Yes	■ No
Additional Plugging Information for Subsequent Report Only  Casing Recovered:		di icci bon	-		a on pla		710000			_	140
asing Recovered: ft. of inch casing									<u> </u>		
Title: Production Engineer Date: Email: theffner@extractionog.com  Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.  COGCC Approved: Date:  CONDITIONS OF APPROVAL, IF ANY: Expiration Date:  Attachment Check List  Mame	Virelin	e Contract	tor:	_			inch cas	_			
Title: Production Engineer Date: Email: theffner@extractionog.com  Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.  COGCC Approved: Date:  CONDITIONS OF APPROVAL, IF ANY: Expiration Date:  Attachment Check List  Mame	Wirelin ype of lowline	e Contract Cement a e/Pipeline I	nd Additives U	Jsed:	per Ru				*Cementing Cor		*ATTACH JOB SUMMARY
Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.  COGCC Approved:  Date:  Expiration Date:  Attachment Check List  Att Doc Num  Name	Wirelin Type of Tlowline Technic	e Contract Cement a s/Pipeline I al Detail/C	nd Additives Unas been abar	Jsed:		ıle 1103	3	Yes	*Cementing Cor	ntractor:	
COGCC Approved: Date:  CONDITIONS OF APPROVAL, IF ANY: Expiration Date:  Attachment Check List  Att Doc Num Name	Wirelin  ype of  lowline  echnic	e Contract Cement a b/Pipeline I al Detail/C	nd Additives Unas been abar	Jsed:		ıle 1103	3	Yes st of my kn	No No	eorrect, and com	
Attachment Check List  Att Doc Num Name	Wirelin Type of Flowline Technic hereby Signed	e Contract Cement a p/Pipeline I al Detail/C	nd Additives Unas been abar comments:	Jsed:		ule 1103	3 o the be	Yes st of my kn	No No Nowledge, true, coint Name: Taylo	eorrect, and com	nplete.
Attachment Check List  Att Doc Num Name	Wirelin Type of Flowline Fechnic hereby Signed Title: Based orders	e Contract Cement a p/Pipeline I al Detail/C certify all r Production on the info	nd Additives Unas been abar Comments: statements manning on Engineer	Jsed: ndoned ade in	this forr	m are, t	to the be	Yes st of my kn Pr ment Repo	No No No No No No No Nowledge, true, coint Name: Taylo	correct, and comor Heffner eeffner@extraction	onog.com  CC Rules and applicable
Att Doc Num Name	Wirelin Type of Flowline Fechnic hereby Signed Title: Based orders	e Contract Cement a p/Pipeline I al Detail/C r certify all r Production on the info and is here C Approve	nd Additives Unas been abar comments: statements materials and Engineer on Engineer ermation provideby approved.	Jsed: ndoned ade in	this forr	m are, t	to the be	Yes st of my kn Pr ment Repo	No No No No No No No Nowledge, true, coint Name: Taylo	correct, and comor Heffner effner@extraction plies with COG	onog.com  CC Rules and applicable te:
	Wirelin Type of Flowline Technic hereby Signed Title: Based orders	e Contract Cement a p/Pipeline I al Detail/C r certify all r Production on the info and is here C Approve	nd Additives Unas been abar comments: statements materials and Engineer on Engineer ermation provideby approved.	Jsed: ndoned ade in	this forr	m are, t	to the be	Yes st of my kn Pr ment Repo	No No No No No No No Nowledge, true, coint Name: Taylo	correct, and comor Heffner effner@extraction plies with COG	onog.com  CC Rules and applicable te:
00919011   WELLBORE DIAGRAM	Wirelin Type of Flowline Fechnic Technic Thereby Signed Title: Based orders COGC	e Contract Cement a b/Pipeline I al Detail/C certify all Production on the info and is here C Approve	nd Additives Unas been abar comments: statements ma on Engineer armation provideby approved.	Jsed: ndoned ade in	this forr	m are, t	to the be	Yes  st of my kn Pr ment Repo	No N	correct, and comor Heffner effner@extraction plies with COG	onog.com  CC Rules and applicable te:
Total Attach: 1 Files	Wirelin Type of Flowline Flowline Fechnic hereby Signed Title: Based orders COGC	e Contract Cement a p/Pipeline I al Detail/C certify all reproduction on the info and is here C Approve TIONS OF	nd Additives Unas been abar comments: statements manning approved. ad: Name	Jsed: ndoned ade in	this forr	m are, t  Date:	to the be	Yes  st of my kn Pr ment Repo	No N	correct, and comor Heffner effner@extraction plies with COG	onog.com  CC Rules and applicable te:

General Comments								
<u>User Group</u>	Comment			<b>Comment Date</b>				
Total: 0 comme	⊥ ent(s)							
	· ,							

Date Run: 10/15/2015 Doc [#400919008] Well Name: HIPPEN 1-32